RobLight

Framing spot, LED

User manual

Item nr.
11613110 Framing spot, black
11613120 Framing spot, grey
11619110 Framing spot custom, black
11619120 Framing spot custom, grey

RobLight

Mounting

Loosen the tilt screw and re-move the optical head from the base.

Drill a hole for the wire (typically Ø8) Mount the base using the supplied screws

Mount the optical head to the base again and rotate into posi-tion.

RobLight

Connect the driver

Connect to mains.

- Blue

+ Red / Brown

Output:
700 mA
constant current

Adjusting the fitting

1: Loosen the finger screw on the base to pan the fitting to the desired position.
Tighten the finger screw again.
2: Tilting the fitting is possible by loosening the finger screw on the base arm.
Tighten when tilted to the wanted position.

RobLight

3: Focus the fitting by sliding the front lens. If a sharp edge is not wanted, slightly blurred edges can be made by defocusing.

4: Adjust the framing blades by sliding and twisting. Please note that the "Image" reacts opposite to your operation.

RobLight

RobLight A/S, Gl. Skagensvej 105 H, DK-9900 Frederikshavn
T: +45 9244 4888, E: info@rob-light.com
www.rob-light.com